



MUL-T-LOCK®

ON LINE UPDATE

Tech. Update

No. 227

Date: 21.06.10



Watch your E-clip!

You have probably noticed that our profile service cylinders always come with the E-clips on the side. This is because the E-clip is often damaged during the removal process. In each and every cylinder manual we ask, over and over again: "Please replace the E-clip every time you take it off the cylinder – with a fresh new E-clip from your pinning kit".

It is very important to make sure that the new E-clip is mounted with the rounded edges facing the cylinder body, and that the E-clip center tooth is inserted into the plug groove.

